



CODICE	øD	CR	l	l1	ød1	Bta	L	ød
CXLRs 5030-05-09	3	0,5	6	9	2,95	16°	50	6
CXLRs 5030-05-12	3	0,5	6	12	2,95	16°	50	6
CXLRs 5040-05-12	4	0,5	8	12	3,85	16°	60	6
CXLRs 5040-05-16	4	0,5	8	16	3,85	16°	60	6
CXLRs 5040-10-12	4	1	8	12	3,85	16°	60	6
CXLRs 5040-10-16	4	1	8	16	3,85	16°	60	6
CXLRs 5060-05-18	6	0,5	12	18	5,85	-	70	6
CXLRs 5060-05-24	6	0,5	12	24	5,85	-	70	6
CXLRs 5060-10-18	6	1	12	18	5,85	-	70	6
CXLRs 5060-10-24	6	1	12	24	5,85	-	70	6
CXLRs 5080-05-24	8	0,5	16	24	7,8	-	70	8
CXLRs 5080-05-32	8	0,5	16	32	7,8	-	70	8
CXLRs 5080-10-24	8	1	16	24	7,8	-	70	8
CXLRs 5080-10-32	8	1	16	32	7,8	-	70	8
CXLRs 5100-05-30	10	0,5	20	30	9,8	-	80	10
CXLRs 5100-05-40	10	0,5	20	40	9,8	-	80	10
CXLRs 5100-10-30	10	1	20	30	9,8	-	80	10
CXLRs 5100-10-40	10	1	20	40	9,8	-	80	10
CXLRs 5100-15-30	10	1,5	20	30	9,8	-	80	10
CXLRs 5100-15-40	10	1,5	20	40	9,8	-	80	10
CXLRs 5100-20-30	10	2	20	30	9,8	-	80	10
CXLRs 5100-20-40	10	2	20	40	9,8	-	80	10
CXLRs 5120-05-36	12	0,5	24	36	11,8	-	80	12
CXLRs 5120-05-48	12	0,5	24	48	11,8	-	100	12
CXLRs 5120-10-36	12	1	24	36	11,8	-	80	12
CXLRs 5120-10-48	12	1	24	48	11,8	-	100	12
CXLRs 5120-15-36	12	1,5	24	36	11,8	-	80	12
CXLRs 5120-15-48	12	1,5	24	48	11,8	-	100	12
CXLRs 5120-20-36	12	2	24	36	11,8	-	80	12
CXLRs 5120-20-48	12	2	24	48	11,8	-	100	12